



# LOM PRAHA s.p.

100 38 PRAHA 10 • 270 ČERNOKOSTELECKÁ STREET

CZECH REPUBLIC

## SERVICE BULLETIN No. M332/83a

*Refers to :* The precision of marking of engine M332.

*Reason:* The certificate of marking of engine was issued for type M332.  
Producer of engine M332 Motorlet Praha equipped of engines M332 with unsuitable label of type with mark M332-Sc.

*Measure:* If there is on the engine label of type M332-Sc as matter of fact it is engine M332.

a) Measure for users of engine M332.

In case that marking M332-Sc is mentioned in Log Book of engine, please correct this name with refer to this bulletin.

The label of engine is not necessary to correct neither to change.

b) Measure for servicemen of engine M332.

During performing of partial repair or overhaul arrange grinding out of label of type. We recommend to perform, when the upper cover of crankcase is taken off. In case that marking M332-Sc is mentioned in Log Book of engine, please correct this name to M332 with refer to this bulletin.

*Note:* In speech and written utterance concerns to engine M332 use types mark M332 only.

*Measure will* Perform of correcting of Log Book - users and repairmen of engine M332.

*be executed:* Perform of correcting label - repairmen of engine M332 during arrangement partial repair or overhaul of engine.

*Material:* It is not necessary.

*Costs:* They is not came.

*Validity:* Date of issue.

*Prague:* May 10, 2001.

Dipl. Ing. J. Pietrik, m.p.

DAR

Dipl. Ing. V. Zasadil, CSc, m.p.

Chief manager of LOM PRAHA s.p.