

# OMNIPOL

PRAHA - ČESKOSLOVENSKO



AVIA  
NÁRODNÍ PODNIK  
PRAHA

## SERVICE BULLETIN

IT IS NECESSARY TO CARRY OUT!

No. M 332/63  
M 337/61

CONCERNS: Mounting of Sc 0377 couplings of distribution drive.

REASON: Completion of bulletin No. M 332/41, M 337/30  
claimed by the Czechoslovak Airlines.

MEASURE TAKEN:

Both the female-keywayed couplings are to be mounted  
with their shorter halves facing to the cam box.

TO BE EFFECTED BY:

The user, when dismounting the cam box for any reason.

EXPENSES TO BE BORNE BY:

No expenses should occur.

Latňany, 10.2.1969.

M. Adamec m.p.

.....  
Producer's Representative

Ing. Homola m.p.

.....  
Customer's Representative

Ing. Holovský m.p.

.....  
Government Air Inspection

Ing. Jirouš m.p.

.....  
Omnipol