



INFORMATION BULLETIN

No. M 462-RF/16

CONCERNS : Information about alterations in the "M 462-RF Aircraft Engine Catalogue of Spare Parts".

REASON : In connection with the design alteration, No. Av - M 462-RF-Z-0733, beginning since the M 462-RF engine of serial No. 11533, has been introduced in service the original design of the oil sump provided with a strainer.

PRECAUTION: In consequence of the above-mentioned fact please note in your "M 462-RF Aircraft Engine Catalogue of Spare Parts" the following alterations, valid from the engine serial No. 11533 on:

Subassembly "13 - OIL SUMP"Pos. 4:

The respective Part No. "M 462-RF-0597" has been altered to "14-02-587" and the Item (Part Description): "Filter screwed fitting c/w nozzle" Part No. M 462-RF-0327", has been replaced with a new part "Filter Brace". Part No. 14-02-509.

Loose parts to Drawing No. 14-702-103:

A new part following after pos. 5 has been introduced: "Pos. 19, 1 pc., Filter lock piece, Part No. 10-02-07."

Pos. items 14 to 18 have been cancelled.

(The respective sketch you will find on the back side of this Bulletin).

10.6.1971

M. Adamec, m.p.

.....
Manufacturers' Representative

Ing. B. Homola, m.p.

.....
Customers' Representative
at Manufacturers' Works

Ing. S. Černocký, m.p.

.....
Representative of Aircraft
Manufacturers

Ing. O. Holovský, m.p.

.....
Representative of Czech Civil
Aviation Inspection

