

**AVIA**

Akciová společnost
Beranových 140
19903 Praha 9 Letňany

INFORMATION BULLETIN

No. M 337/75b

It is recommended

- REFERS TO:** Cancellation of the partial engine inspection in the half of the working hours till Overhaul, i.e. at 500 hours, for M 337 engines, that were in operation all this time using oils Aeroshell W 100 or Elf 100 AD.
- REASON:** Due to the committee inspection of the engines having the 500 flight hours after Overhaul and also due to the state of engines determined during Overhaul, for engines using the above mentioned oils in the operation.
- MEASURES:** Special measures does not arise.
- REALISATION:** The user
- COSTS:** None
- BULLETIN ACTIVE:** from September 1, 1991

Ing. P. Měříčka, m.e.

Propeller manufacturer
representative

Ing. B. Homola, m.e.

Customer's representative
with propeller manufacturer

Ing. J. Beneš

State Civil Inspection