

**INFORMATION BULLETIN**

No. M 462-RF/8

RE : Handbook "Technical Description and Servicing
Instructions of M 462-RF Aircraft Engine".

REASON: Supplementing of basic technical data of engine.

MEASURES:

Supplement in the handbook "Technical Description and
Servicing Instructions of M 462-RF Aircraft Engine"
on page 10, in paragraph "2.2.1 General Data" a new
point :

17. a) Out-of-true of reduction shaft - max. 0.14 mm
measured 23 mm from the
bearing surface of the
reducer nut.

b) Axial clearance of reduction
shaft - max. 0.35 mm

March 26, 1968

..... Ing. Kyncl m.p.
Representative of the engine
makers

..... Ing. Homola m.p.
Buyer's representative