

List of valid Service Letters of LOM PRAHA s.p. for Piston Engines and Propellers

	Date of issue:	Concerning:	Letter category:	Note:
0001 / 2004	March 15, 2004	Principles of mixing of engine oils for the aircraft piston engines of LOM PRAHA s.p. Oil changes entering into the engine logbook.	M	
0002 / 2004	August 25, 2004	Cancellation of the M332/64 and M337/66 bulletins	M	
0003 / 2005	March 30, 2005	Cancellation of the M337A/9b and M337AK/4b bulletins	M	
0004 / 2005	May 25, 2005	Introduction of the ultrasonic flaw detection inspection of connecting rods at GO	О	
0005 / 2005	September 12, 2005	Cancellation of bulletins	M	
0006 / 2006	May 15, 2006	Introduction of the provision of the change service information on the web pages of LOM PRAHA s.p www.lompraha.cz	М	
0007 / 2012 / R1	July 4, 2012	Service Letter revision. Introduction of spark plugs L22.62A for the engines M132, M137, M332 and M337 of all versions.	M	
0008 / 2007	December 17, 2007	During transportation of two units of the M337C engines S/N 159021072 and 15971068 the identification labels and engine log books have been stolen. Taking measures so that the identification data cannot be misused.	М	
0009/R1/2020	February 17, 2020	Announcement of persons authorized by LOM PRAHA s.p. to prolong the operational limits of the M337, M337A, M337AK, M137A, M137AZ engines under the valid information bulletins and to inspect the engines M337, M332, M137, M132 of all versions after 15 years of operation under the valid mandatory bulletin. Service Letter revision.	М	



0010/2009	June 3, 2009	Information on the LOM ASSISTANCE system cancellation. Cancellation of the periodical inspection after 100 hours of operation or 12 months for the engines of model lines M337, M332, M137 and M132 of all versions maintained in the LOM ASSISTANCE system.	М	
0011/2009	June 22, 2009	List of new documents issued during May and June 2009.	M	
0012/2009	August 14, 2009	Additional survey to the mandatory bulletin No. LOM-MB 03a/2009. It is necessary to find out if the list of the engines specified in the bulletin No. LOM-MB-03a/2009 is complete or there are other engines, extended in this way, outside this register.	М	-
0013/2014	November 12, 2014	Safety recommendations and information.	M	
0014/2014	November 18, 2014	Safety recommendations and information.	M	Englishment June 07, 2016.
0015/2016	July 15, 2016	Safety recommendations and information.	M	
0016/2018	November 16, 2018	Engines M132, M332, M137 and M337all types, versions and modifications. Questions about extensions of the calendar engine operating period. Support to released and canceled bulletins for unmistakable interpretation.	М	
0017/2018	-	Cancelled.	-	-

Date of the last revision: December 22, 2022.